



SUPER KING AIR B200
No.1 Engine Component Overhaul Status
Pratt & Whitney Canada
PT6A-42

Registration : PK - YGT
 Serial No. : BL-138
 ENGINE S/n : PCE - 94559

Total Time : 9116
 Total Landing : 7338
 Engine TT : 8796
 Date : 03-Dec-15

No.	Task Card	Work Card	Ref.	Description	Part Number	Serial Number	Frequency		Last Compliance			Time at Install		Next Due				Time Remaining	
							Hrs	Mos	Engine Hours	Aircraft Hours	Date	Hrs	Days	Eng Hrs	A/C Hrs	Date	Ldgs	Hrs	Days
CHAPTER 71																			
1	710010	71,010		Engine Overhaul	PT6A-42	PCE 94559	3600		5826		29-May-02	0	0	9426				630	
CHAPTER 72																			
1	720142	72-040		Replacement of the Engine Flameble fluid Hose				120	7674	7994	7-Sep-10	0	0			4-Sep-20			1736
CHAPTER 73																			
1	730700	73,070		Engine Fuel Collector Unit	476284	UNK			0		8-Nov-92	0	0						
2	731010	73,010	EMM73-10-02	Engine Driven Fuel Pump	025323-300-03	8041	3600		8578	8898	28-Feb-13	0	0	12178	12498			3382	
3	731060	73,070	EMM73-10-01	Engine Oil to Fuel Heater	10975-J	2091	3600		5825		18-May-04	0	0	9425	3600			629	
4	731070			Engine Fuel Flow Divider	3036640	1491	3600		5825		18-May-04	0	0	9425	3600			629	
5	731080	73,080		Engine Fuel Boost Pump	91-380003-3	B8106			0		8-Nov-92	0	0						
6	731090	73,090	EMM73-20-00	Engine Fuel Control Unit	3244758-13	B12851	3600		5825		18-May-04	0	0	9425	3600			629	
7	731095	73,100		Engine Fuel Control Unit Body and Bearing			1800	72	7675	7995	13-Feb-10	0	0	9475	9795	12-Feb-16		679	70
8	731110	73,120	EMM73-10-09	Engine Torque Limiter	33244707-8	B10220	3600		5825		18-May-04	0	0	9425	3600			629	
9	732010	73,130		Engine Fuel Flow Transmitter.	90-380009-7	UNK			0		8-Nov-92	0	0						
10	733020	73,140	EMM73-10-09	Replacement of the Engine P3 Air Filter.	3059788-01	UNK	1000		8405	8725	30-Jul-12	0	0	9405	9725			609	
CHAPTER 74																			
1	740010	74,010	EMM74-10-00	Engine Igniter Exiter	3014365	UNK						0	0						
2	740020	74,030	EMM74-20-00	Engine 4 O'Clock Igniter	CH434055	UNK						0	0						
3	740040	74,040	EMM74-20-00	Engine 9 O'Clock Igniter	CH34055	UNK						0	0						
4	740070	74,050		Engine Auto Igniter Pressure Switch.	MS24658-230	UNK						0	0						
CHAPTER 75																			
1	750010	75.010	EMM75-30-00	Engine High Pressure Bleed Valve	31000922-05	12A138	3600		5825		18-May-04	0	0	9425	3600			629	
2	750020	75.020	EMM75-30-00	Engine Low Pressure Bleed Valve	31000923-02	2F463	3600		5825		18-May-04	0	0	9425	3600			629	
CHAPTER 76																			
1	760301	76.020		Change L/H Engine Power Lever Pin (Pedestal)	101-524181-1	UNK			0		8-Nov-92	0	0						
CHAPTER 77																			
1	770101	77.010		Engine Turbine Tach Indicator	50-380034-3	2384			4126		6-Aug-01	0	0						
2	770111	77.020		Engine Torque Pressure Indicator	101-384008-3	UNK			0		11-Aug-92	0	0						
3	770121	77.030		Engine Turbine Interstage Temp Indicator	50-389102-15	UNK			0		11-Aug-92	0	0						
4	770010	77.010		Engine Turbine Tach Generator	50-689023-5	4288-2-113					10-Jul-98	0	0						



SUPER KING AIR B200
No.1 Engine Component Overhaul Status
Pratt & Whitney Canada
PT6A-42

Registration : PK - YGT
 Serial No. : BL-138
 ENGINE S/n : PCE - 94559

Total Time : 9116
 Total Landing : 7338
 Engine TT : 8796
 Date : 03-Dec-15

No.	Task Card	Work Card	Ref.	Description	Part Number	Serial Number	Frequency		Last Compliance			Time at Install		Next Due				Time Remaining	
							Hrs	Mos	Engine Hours	Aircraft Hours	Date	Hrs	Days	Eng Hrs	A/C Hrs	Date	Ldgs	Hrs	Days
5	770020	77.020		Engine Torque Pressure Transmitter	101-389005-2	1242			1632		20-Nov-97	0	0						
6	770030	77.030		Engine Turbine Temperature Harnes.	3112214-01	UNK			4881		28-Jun-02	0	0						
CHAPTER 78																			
1	780101	78.010		Engine L/H Exhaust / Wed Assy	101-950016-23	UNK			0		8-Nov-92	0.00	0						
2	780106	78.010		Engine R/H Exhaust / Wed Assy	101-950023-3	UNK			8301		16-May-11	0.00	0						
CHAPTER 79																			
1	790116	79.080		Engine Oil Temperature / Pressure Ind.	101-384122-7	UNK			0			0.00	0						
2	792005	79.010		Change Oil Pressure Transducer	101-389023-5	UNK			3825		11-Aug-92	0.00	0						
3	790020	79.020		Change Engine Chip Detector	3019373	UNK			3825		18-May-04	0.00	0						
4	790050	79.050		Replacement of the Engine High Capacity Oil Filter	3059258-01	UNK	1000		8405		30-Jul-12	0.00	0	9405	1000			609	
5	790080	79.090		Change Engine Oil Pressure Transmitter.	101-389-023-5	4288-2-305			5825		18-May-04	0.00	0						
6	790090	79.100		Change Engine Oil Temperature Bulb	MS28034-3	UNK			5825		18-May-04	0.00	0						